

345 Carlingview Drive Toronto, ON M9W 6N9

Tel.: 416.734.3300 Fax.: 416.231.1626 Toll Free: 1.877.682.8772 www.tssa.org

Safety Information Bulletins Revised October 15, 2018 <u>Valid Bulletins</u>

Bulletin #	Issue Date	Title	
SB00-1	May 5, 2000	Technical Circulars issued prior to May 5, 1997 for the purposes of the Boilers and Pressure Vessels Act of Ontario	
SB00-2 Rev.1	August 27, 2001	Modifications/Alterations to Registered Conventional Piping Systems	
SB00-3 Rev. 3	November 22, 2001	Ontario Requirements for the Repair of Pressure Relief Valves	
SB00-4	May 5, 2000	Fitting Registration Program	
SB00-6 Rev.1	August 27, 2001	Alteration of Registered Fittings	
SB00-7 Rev. 4	October 4, 2001	Guide for the Scope of Services requiring Registration and Inspection of Pressure Piping Systems by Boilers and Pressure Vessels Safety Division for Installation in the Province of Ontario	
SB00-8	May 5, 2000	Restricted Use of PVC Pipe	
SB00-9	May 5, 2000	ASME/ASTM A 193 – $\underline{\rm B7M}$ – 89 Studs/Bolts and A 194 – 2HM – 88 Nuts	
SB00-11	May 5, 2000	Cast Iron Valves and Fitting in Ammonia Refrigeration Services	
SB00-14	May 5, 2000	Exposure to Asbestos	
SB00-15 Rev.2	February 13, 2003	Water Treatment Facilities	
SB00-16	May 5, 2000	Validity of Registered Designs	
SB00-17 Rev. 1	November 22, 2001	SA 515 Materials	
SB00-18 Rev.3	October 26, 2009	Deaerators and Hot Water Storage Tanks - Periodic Inspection Intervals	
SB02-01 Rev. 1	April 24, 2013	Repair and Alteration Certification Program Requirements	
SB02-02 Rev.2	April 24, 2013	Requirements for Manufacturers and Installers of Pressure Piping Parts and Systems	
SB05-01	July 29, 2005	Guideline for Maintenance Replacement of Mechanically assembled items in existing Pressure Piping systems regulated by: The Ontario Technical Standards & Safety Act, Boilers & Pressure Vessels Regulation	
SB05-02	July 29, 2005	Hot Tap & Line Stopping Guidelines For Equipment Regulated by The Ontario Boilers & Pressure Vessels Regulation	
SB06-01	August 25, 2006	Refrigeration Piping Fabrication, Installation, Repair or Alteration	
SB09-01	October 26, 2009	Rerating of Boilers & Pressure Vessels	
SB12-01	May 24, 2012	Pressure Relief Device Discharge	
SB13-01	January 9, 2013	Ontario Certificate of Competency for Insurers	



345 Carlingview Drive Toronto, ON M9W 6N9

Tel.: 416.734.3300 Fax.: 416.231.1626 Toll Free: 1.877.682.8772 www.tssa.org

Recent Revised Bulletins - Previous Issues

Bulletin #	Issue Date	Title	Previous Issue
SB00-2 Rev.1	August 27, 2001	Modifications/Alterations to Registered Conventional Piping Systems	Replaces SB00-2, Issued May 5, 2000
SB00-3 Rev. 3	November 22, 2001	Ontario Requirements for the Repair of Pressure Relief Valves	Replaces SB00-3 Rev. 2, Issued August 27, 2001
SB00-6 Rev.1	August 27, 2001	Alteration of Registered Fittings	Replaces SB00-6, Issued May 5, 2000
SB00-7 Rev. 4	October 4, 2001	Guide for the Scope of Services requiring Registration and Inspection of Pressure Piping Systems by Boilers and Pressure Vessels Safety Division for Installation in the Province of Ontario	Replaces SB00-7 Rev. 3, Issued Sept. 27, 2001
SB00-15 Rev. 2	February 13, 2003	Water Treatment Facilities	Replaces SB00-15 Rev. 1, Issued August 27, 2001
SB00-17 Rev. 1	November 22, 2001	SA 515 Materials	Replaces SB00-17, Issued May 5, 2000
SB00-18 Rev. 3	October 26, 2009	Deaerators and Hot Water Storage Tanks – Periodic Inspection Intervals	Replaces SB00-18 Rev.2 Issued June 18, 2003
SB02-02 Rev.2	April 24, 2013	Requirements for Manufacturers and Installers of Pressure Piping Parts and Systems	Replaces SB02-02, Rev.1 Issued April 24, 2003
SB02-01 Rev.1	April 24, 2013	Repair and Alteration Certification Program Requirements	Replaces SB02-01 January 30, 2002
SB05-2 REV.2	OCT 15, 2018	Hot Tap and Line Stopping for Pressure Equipment	Replaces SB05-2 Rev. 1 Issued Sept 8, 2006



345 Carlingview Drive Toronto, ON M9W 6N9

Tel.: 416.734.3300 Fax.: 416.231.1626 Toll Free: 1.877.682.8772

www.tssa.org

Void Bulletins

Bulletin #	Issue Date	Title	Status
SB00-5 Supersedes T1-94 issued Jan. 28, 1994	May 5, 2000	Hockey, Skating or Curling Ice Rinks using Group 2 Refrigerant: Paragraph 6 of Section 23(3) of Regulation 59	Cancelled – See Code Adoption Document, dated June 1, 2001 Section 5.
SB00-10 Supersedes T4-92 issued Jan. 21, 1992	May 5, 2000	Pressure Vessel Inspection Openings	Cancelled – See Code Adoption Document, dated June 1, 2001, Section 13(5).
SB00-12 Supersedes T2-91 issued July 23, 1991	May 5, 2000	Requalification of Welders, Welding Operators and Brazers	Cancelled – See Code Adoption Document, dated June 1, 2001 Section 6.
SB00-13	May 5, 2000	Canadian Registration Numbers	
SB00-19	Sept 11, 2009	Canadian Interprovincial Guideline for Pressure Relief Valves	Cancelled – See Amendment to the Code Adoption Document dated May 1, 2008. This information can be found in CSA B51- 03 Annex H.
SB00-20 Rev.1 Superseded by Advisory BPV-18-02	Sept 4, 2018	Boilers & Pressure Vessels/Fuels Safety Division Involvement in Hydrocarbon Piping Systems	Cancelled – See Advisory BPV-18-02, Boilers and Pressure Vessels Safety & Fuels Safety Programs Involvement in Piping Systems in Fuel Services.