

Skirt Panels and Balustrades

If panels on either side of the escalator are worn, damaged, out of alignment or defective –
SHUT DOWN

